



MDOT RC-1514



# **Combining Link Slab, Deck Sliding over Backwall, and Revising Bearings**

**FINAL REPORT – AUGUST 2008  
(APPENDICES)**



**Western Michigan University**  
Department of Civil & Construction Engineering  
College of Engineering and Applied Sciences

**Research**

Intentionally left blank

# **COMBINING LINK SLAB, DECK SLIDING OVER BACKWALL, AND REVISING BEARINGS (Appendices)**

**Project Manager: Mr. Roger Till, P.E.**

**Submitted to:**



**Submitted by**

Dr. Haluk Aktan, P.E.  
Professor & Chair  
(269) – 276 – 3206  
[haluk.aktan@wmich.edu](mailto:haluk.aktan@wmich.edu)

Dr. Upul Attanayake, E.I.T  
Assistant Professor  
(269) – 276 – 3217  
[upul.attanayake@wmich.edu](mailto:upul.attanayake@wmich.edu)

Mr. Evren Ulku  
Graduate Research Assistant  
(313) – 577 – 3785  
[evren@eng.wayne.edu](mailto:evren@eng.wayne.edu)



**Western Michigan University**  
Department of Civil & Construction Engineering  
College of Engineering and Applied Sciences  
Kalamazoo, MI 49008  
Fax: (269) – 276 – 3211

Intentionally left blank

APPENDIX A







Figure A-1. Plan and elevation of S04-1, 2 of 63174



**Figure A-2. Plan and elevation of S08 of 41027**




**Figure A-3. Plan and elevation of S12-3 and 4 of 25042**



S12-7 OF 25042  
S12-8 OF 25042

**Figure A-4. Plan and elevation of S12-7 and 8 of 25042**





**Figure A-5. Plan and elevation of B01 of 10042 and B01 of 51041**

## APPENDIX B

Field inspection data of the following bridges

No	Bridge ID	Description	Inspection Date	Remarks
1	S04-1-63174	I-75 NB over 13 Mile Rd	12/03/2006	Detailed inspection
2	S04-2-63174	I-75 SB over 13 Mile Rd	12/03/2006	Photo log
3	S08-41027	I-196 EB over Monroe Av	11/04/2006	Detailed inspection
4	B01-10042	M115 over Betsie Rive	11/04/200	Detailed inspection
5	S12-3-25042	I-69 EB over I-75	11/05/2006	Detailed underside inspection
6	S12-4-25042	I-69 WB over I-75	11/05/2006	Detailed inspection
7	S12-7-25042	I-69 EB Ramp over I-75	11/05/2006	Detailed inspection
8	S12-8-25042	I-69 WB Ramp over I-75	11/05/2006	Detailed inspection

# FIELD INSPECTION TEMPLATE

For S04-1 OF 63174 ON I-75 NB OVER 13 MILE ROAD , OAKLAND COUNTY, METRO REGION



## OVERVIEW PLAN

\*\*STAY-IN-PLACE FORMS  
\*\*NO EROSION OR SETTLEMENTS  
OF BACKFILL  
\*\*P1-BRIDGE PLATE  
\*\*EXPANSION JOINTS @ SLEEPER  
SLABS ARE FILLED WITH DEBRIS  
AND THEY CONTAIN CRACKS  
SHOWING THAT EXPANSION  
JOINTS ARE FUNCTIONING

P 1- BRIDGE PLATE

SOUTH PIER  
PIER 1

NORTH PIER  
PIER 2

P 2  
P 3  
P 4  
P 5


P 6  
P 7  
P 8

P 9  
P 10  
P 11  
P 12

P 12  
P 13  
P 14

P 15  
P 16  
P 17  
P 18

P 19  
P 20  
P 21



INSPECTOR:

DATE: 12/03/06


PAGE: 1/ 13

FIELD INSPECTION TEMPLATE

Bridge ID: S04-1 of 63174

\*\*north is out of the page.

SOUTH ABUTMENT



INSPECTOR:

DATE: 12/03/06


PAGE: 11/13

FIELD INSPECTION TEMPLATE  
Bridge ID: S04-1 of 63174

S APP SLAB



SOUTH APPROACH SLAB



INSPECTOR:

DATE: 12/03/06


PAGE: 2/13

S SPAN 1

FIELD INSPECTION TEMPLATE  
 Bridge ID: S04-1 of 63174



BRIDGE DECK  
 SOUTH SPAN 1



P 25  
 P 26  
 P 27  
 P 28

P 22  
 P 23  
 P 24  
 P 25

P 40  
 P 41  
 P 42  
 P 43

EFF (UNDER SIDE)

CRACKING  
 EFF

INSPECTOR:

DATE: 12/03/06


PAGE: 4/13

S SPAN 2

FIELD INSPECTION TEMPLATE  
Bridge ID: S04-1 of 63174



BRIDGE DECK  
SOUTH SPAN 2



EFF

INSPECTOR:

DATE: 12/03/06

PAGE: 5/13


S SPAN 3

FIELD INSPECTION TEMPLATE  
 Bridge ID: S04-1 of 63174



BRIDGE DECK  
 SOUTH SPAN 3

\*\*CANNOT SEE IF CRACKS GO  
 ALL THE WAY THROUGH  
 SINCE IT IS STAY-IN-PLACE FORM



INSPECTOR:

DATE: 12/03/06

PAGE: 6/13



FIELD INSPECTION TEMPLATE


Bridge ID: S04-1 of 63174



N

NORTH APPROACH SLAB

N APP SLAB



INSPECTOR:

DATE: 12/03/06

PAGE: 3/13

Bridge ID: S04-1 of 63174

\*\*north is into the page.

## NORTH ABUTMENT

INSPECTOR:

DATE: 12/03/06


PAGE: 10/13

FIELD INSPECTION TEMPLATE

Bridge ID: S04-1 of 63174

\*\*north is into the page.

SOUTH PIER (PIER 1)



INSPECTOR:

DATE: 12/03/06

PAGE: 12/13

FIELD INSPECTION TEMPLATE

Bridge ID: S04-1 of 63174

\*\*north is out of the page.

NORTH PIER (PIER 2)

SOUTH SIDE																		
	EBM1		EBM2		EBM3		EBM4		EBM5		EBM6		EBM7		EBM8		EBM9	
	↑					↑	↑				↑	↑		↑				
	P79					P80	P81				P82	P83		P84				
NORTH SIDE																		

INSPECTOR:

DATE: 12/03/06

PAGE: 13/13


# FIELD INSPECTION TEMPLATE

For S04-2 OF 63174 ON I-75 SB OVER 13 MILE ROAD , OAKLAND COUNTY, METRO REGION

\*\*NO SIGNS OF  
EROSION OF BACKFILL  
\*\*STAY-IN-PLACE FORMS  
\*\*EXPANSION JOINTS  
AT SLEEPER SLABS  
ARE FILLED WITH DEBRIS  
\*\*THERE WERE CRACKS  
SHOWING THAT JOINTS  
WORK  
\*\*LINK SLABS SHOWED  
NO CRACKING ON TOP



## OVERVIEW PLAN



INSPECTOR:

DATE: 12/03/06

PAGE: 1/ 13

Bridge ID: S04-2 of 63174

SOUTH ABUTMENT

	EBM1		EBM2		EBM3		EBM4		EBM5		EBM6		EBM7		EBM8		EBM9	
P 1 P 2	P 3 P 4		P 5 P 6		P 7		P 8 P 9		P 10 P 11		P 12 P 13		P 14		P 15 P 16	P 17 P 18		P 19

PAGE: 11/13

FIELD INSPECTION TEMPLATE  
Bridge ID: S04-2 of 63174

S APP SLAB



N

SOUTH APPROACH SLAB

SLEEPER SLAB				

5'

INSPECTOR:

DATE: 12/03/06


PAGE: 2/13

S SPAN 1

FIELD INSPECTION TEMPLATE  
Bridge ID: S04-2 of 63174



BRIDGE DECK  
SOUTH SPAN 1



INSPECTOR:

DATE: 12/03/06

PAGE: 4/13




S SPAN 2

FIELD INSPECTION TEMPLATE  
 Bridge ID: S04-2 of 63174



BRIDGE DECK  
 SOUTH SPAN 2



INSPECTOR:

DATE: 12/03/06

PAGE: 5/13


S SPAN 3

FIELD INSPECTION TEMPLATE

Bridge ID: S04-2 of 63174



BRIDGE DECK  
SOUTH SPAN 3



INSPECTOR:

DATE: 12/03/06

PAGE: 6/13


N APP SLAB

FIELD INSPECTION TEMPLATE

Bridge ID: S04-2 of 63174



NORTH    APPROACH SLAB



INSPECTOR:

DATE: 12/03/06

PAGE: 3/13

FIELD INSPECTION TEMPLATE

Bridge ID: S04-2 of 63174

\*\*north is into the page.

NORTH ABUTMENT

EBM9	EBM8	EBM7	EBM6	EBM5	EBM4	EBM3	EBM2	EBM1	
									P64 P65
P47									
P43 P44	P45 P46		P48 P49	P50 P51	P52 P53	P54 P55	P56 P57	P58 P59	P60 P61
P62 P63									

42 →

INSPECTOR:

DATE: 12/03/06

PAGE: 10/13

FIELD INSPECTION TEMPLATE  
Bridge ID: S04-2 of 63174

\*\*north is into the page.

SOUTH PIER (PIER 1)

NORTH FACE																
EBM9		EBM8		EBM7		EBM6		EBM5		EBM4		EBM3		EBM2		EBM1
<div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> <div>P23P24P25P26P27P28</div>																
SOUTH FACE																

INSPECTOR:

DATE: 12/03/06

PAGE: 12/13

FIELD INSPECTION TEMPLATE

Bridge ID: S04-2 of 63174

\*\*north is out of the page.

NORTH PIER (PIER 2)

SOUTH FACE																	
EBM1		EBM2		EBM3		EBM4		EBM5		EBM6		EBM7		EBM8		EBM9	
P39																	
P40																	
P41																	
NORTH FACE																	

INSPECTOR:

DATE: 12/03/06

PAGE: 13/13


# FIELD INSPECTION TEMPLATE

For S08 of 41027 EASTBOUND I-196 OVER MONROE AVE, KENT COUNTY GRAND REGION



## OVERVIEW PLAN

\*\*DECK WAS NOT  
INSPECTED ON 11/04/06  
\*\*STEEL BEAM BRIDGE  
STAY-IN-PLACE FORM



INSPECTOR:

DATE: 11/04/06

PAGE: 1/ 13

# FIELD INSPECTION TEMPLATE

Bridge ID: S08 of 41027

\*\*N/W is out of the page.

S/ E ABUTMENT

		EBM1		EBM2		EBM3		EBM4		EBM5		EBM6		EBM7		EBM8	
BRIDGE ID P79 → P80 →																	
		<div style="text-align: right; margin-right: 50px;"> P67 P68 P69 P70 P71 </div>															
P81 P82 → P83 P84		<div style="text-align: center;"> 0.005" </div>															
		<div style="text-align: center;"> BEARING DEFORMING </div>															
MINOR CRACK		<div style="display: flex; justify-content: space-between;"> <div style="width: 15%;"> P76 P77 P78 </div> <div style="width: 15%;"> P72 P73 P74 P75 </div> <div style="width: 15%;"> P62 P63 P64 P65 P66 </div> <div style="width: 15%;"> P59 P60 P61 </div> <div style="width: 15%;"> P52 P53 P54 P55 P56 P57 P58 </div> <div style="width: 15%;"> P48 P49 P50 P51 </div> <div style="width: 15%;"> P41 P42 P43 P44 P45 P46 P47 </div> <div style="width: 15%;"> P36 P37 </div> <div style="width: 15%;"> P35 </div> </div>															
		<div style="display: flex; justify-content: space-between;"> <div style="width: 15%;"> 0.005" </div> <div style="width: 15%;"></div> <div style="width: 15%;"></div> <div style="width: 15%;"></div> <div style="width: 15%;"> 0.030" </div> <div style="width: 15%;"> 0.025" </div> <div style="width: 15%;"> 0.030" GROVE CRACK </div> <div style="width: 15%;"> 0.050" </div> </div>															
		<div style="text-align: right; margin-right: 50px;"> P38 P39 P40 </div>															


INSPECTOR:

DATE: 11/04/06

PAGE: 11/13



Bridge ID: S08 of 41027



A large black arrow pointing left towards the letter 'z'.

[illegible]

DATE: 11/04/06


29

FIELD INSPECTION TEMPLATE  
Bridge ID: S08 of 41027

S/E SPAN 1



BRIDGE DECK  
S/E SPAN 1




# FIELD INSPECTION TEMPLATE

Bridge ID: S08 of 41027

S/E SPAN 2



BRIDGE DECK  
S/E SPAN 2




S/E SPAN 3

FIELD INSPECTION TEMPLATE  
 Bridge ID: S08 of 41027



BRIDGE DECK  
 S/E SPAN 3




INSPECTOR:

DATE: 11/04/06  
 PAGE: 6/13

Bridge ID: S08 of 41027

Bridge ID: S08 of 41027

N/W APP SLAB



N/W APPROACH SLAB

SLEEPER SLAB

INSPECTOR:

DATE: 11/04/06

PAGE: 3/13

Bridge ID: S08 of 41027

N/W ABUTMENT

34


# FIELD INSPECTION TEMPLATE

For B01 of 10042 ON M115 OVER BETZIE RIVER , BENZIE COUNTY, NORTH REGION

\*\*NO STAY-IN-PLACE  
FORM

N

OVERVIEW PLAN



INSPECTOR:


DATE: 11/04/06

PAGE: 1/ 13

FIELD INSPECTION TEMPLATE  
Bridge ID: B01 OF 10042

\*\*north is out of the page.

S/ E ABUTMENT



INSPECTOR:


DATE:

PAGE: 11/13



SE APP SLAB

FIELD INSPECTION TEMPLATE  
 Bridge ID: B01 OF 10042



INSPECTOR:

DATE:


PAGE: 2/13

INSPECTOR:

FIELD INSPECTION TEMPLATE  
Bridge ID: B01 OF 10042

BRIDGE DECK  
S/E SPAN 1

S/E SPAN 1



INSPECTOR:

DATE:


Note: Cracking  
through  
Middle of Link Slab  
Not at Joint

PAGE: 4/13

FIELD INSPECTION TEMPLATE  
Bridge ID: B01 OF 10042

BRIDGE DECK  
S/E SPAN 2

S/E SPAN 2



INSPECTOR:


DATE:

PAGE: 5/13

FIELD INSPECTION TEMPLATE  
Bridge ID: B01 OF 10042

BRIDGE DECK  
S/E SPAN 3

S/E SPAN 3



INSPECTOR:

DATE:

PAGE: 6/13


FIELD INSPECTION TEMPLATE

Bridge ID: B01 OF 10042

N/W APP SLAB



N/W APPROACH SLAB



INSPECTOR:


DATE:

PAGE: 3/13

FIELD INSPECTION TEMPLATE  
Bridge ID: B01 OF 10042

\*\*north is into the page.

N/W ABUTMENT



INSPECTOR:


DATE:

PAGE: 10/13

# FIELD INSPECTION TEMPLATE

For S12-3 OF 25042 ON I-69 EB OVER I-75, GENESEE COUNTY, BAY REGION

\*\*EXPANSION JOINTS  
ARE DIRT-FILLED AND  
WITH CRACKS SHOWING THAT  
THEY WORK



INSPECTOR:


DATE: 11/05/06

PAGE: 1/ 16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-3 of 25042

\*\*north is out of the page.

S/ W ABUTMENT



INSPECTOR:


DATE:

PAGE: 13/16




FIELD INSPECTION TEMPLATE  
Bridge ID: S12-3 of 25042

SW APP SLAB



S/W APPROACH SLAB



INSPECTOR:


- P 76 →
- P 77
- P 78
- P 79
- P 80
- P 81
- P 82

DATE:

PAGE: 2/16



FIELD INSPECTION TEMPLATE  
Bridge ID: S12-3 of 25042



INSPECTOR:

DATE:


PAGE: 5/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-3 of 25042

S/W SPAN 3

BRIDGE DECK

S/W SPAN 3



INSPECTOR:

DATE:


PAGE: 5/16

# FIELD INSPECTION TEMPLATE

Bridge ID: S12-3 of 25042

S/W SPAN 4

BRIDGE DECK  
S/W SPAN 4



INSPECTOR:


DATE:

PAGE: 5/16


FIELD INSPECTION TEMPLATE

Bridge ID: S12-3 of 25042

N/E APP SLAB



N/E APPROACH SLAB



INSPECTOR:

DATE:


→  
P 98 P 103  
P 99 P 104  
P 100 P 105  
P 101 P 106  
P 102 P 107

PAGE: 3/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-3 of 25042

\*\*north is into the page.

N/E ABUTMENT



INSPECTOR:

DATE:


PAGE: 12/16

FIELD INSPECTION TEMPLATE

For S12-4 OF 25042 ON I-69 WB OVER I-75 , GENESEE COUNTY, BAY REGION



OVERVIEW PLAN



INSPECTOR:

DATE: 11/05/06

PAGE: 1/ 16




FIELD INSPECTION TEMPLATE  
Bridge ID: S12-4 of 25042

\*\*north is out of the page.

\*\*DEBRIS ACCUM.  
BTW. BACKWALL  
& ABUTMENT

S/ W ABUTMENT



INSPECTOR:


DATE:

PAGE: 13/16

SW APP SLAB


# FIELD INSPECTION TEMPLATE

Bridge ID: S12-4 of 25042



S/W APPROACH SLAB

\*\*JOINT BETWEEN SLEEPER SLAB & PAVEMENT NOT VISIBLE



INSPECTOR:

DATE:


PAGE: 2/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-4 of 25042

S/W SPAN 1



BRIDGE DECK  
S/W SPAN 1




FIELD INSPECTION TEMPLATE  
Bridge ID: S12-4 of 25042

S/W SPAN 2



BRIDGE DECK  
S/W SPAN 2



INSPECTOR:

DATE:


PAGE: 5/16

FIELD INSPECTION TEMPLATE  
 Bridge ID: S12-4 of 25042



BRIDGE DECK  
 S/W SPAN 3

S/W SPAN 3




S/W SPAN 4

FIELD INSPECTION TEMPLATE  
 Bridge ID: S12-4 of 25042



BRIDGE DECK  
 S/W SPAN 4




INSPECTOR:

DATE:


PAGE: 7/16

Bridge ID: S12-4 of 25042

N/E APP SLAB



N/E APPROACH SLAB



DATE:

59

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-4 of 25042

\*\*north is into the page.

N/E ABUTMENT

SPALL UNTIL  
REBAR

BEARING IN  
GOOD COND.

BEARING LOST  
DEBRIS ACC.

P 40  
P 41  
P 42

P 59

EBM4	EBM3	EBM2	EBM1
0.040"		0.010"-0.015"	
P 43 P 44 P 45	P 46 P 47 P 48	P 49 P 50 P 51	P 54 P 55
0.010"	CJ 0.015"	0.01"	0.015"-0.020"
		CJ GAP	CR LEAKAGE

INSPECTOR:

DATE:

PAGE: 12/16



Bridge ID: S12-4 of 25042

BEAM S/W SPAN 1


PAGE: 8/16

# FIELD INSPECTION TEMPLATE

Bridge ID: S12-4 of 25042

\*\*north is out of the page.

## PIER 3




INSPECTOR:

DATE:

PAGE: 16/16

# FIELD INSPECTION TEMPLATE

For S12-7 OF 25042 I-69 RAMP EB OVER I-75, GENESEE COUNTY, BAY REGION




INSPECTOR:

DATE: 11/05/06

PAGE: 1 / 16


Bridge ID: S12-7 of 25042

S/ W ABUTMENT



SW APP SLAB


FIELD INSPECTION TEMPLATE  
Bridge ID: S12-7 of 25042



S/W APPROACH SLAB

EXPANSION JOINT IS  
1/2 DIRT FILLED

- P 109
- P 110
- P 111
- P 112
- P 113
- P 114
- P 115



INSPECTOR:


DATE:

PAGE: 2/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-7 of 25042

BRIDGE DECK  
S/W SPAN 1

S/W SPAN 1



INSPECTOR:


DATE:

PAGE: 4/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-7 of 25042

S/W SPAN 2

BRIDGE DECK  
S/W SPAN 2




INSPECTOR:

DATE:

PAGE: 5/16

BRIDGE DECK  
S/W SPAN 3

S/W SPAN 3



PAGE: 6/16




FIELD INSPECTION TEMPLATE  
Bridge ID: S12-7 of 25042

BRIDGE DECK

S/W SPAN 4

S/W SPAN 4




INSPECTOR:

DATE:

PAGE: 7/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-7 of 25042

N/E APP SLAB



N/E APPROACH SLAB

P 85  
P 86  
P 87  
P 88  
P 89  
P 90  
P 91  
P 92



NO INDICATION OF START  
OF APPROACH SLAB

5'



P 78  
P 79  
P 80  
P 81  
P 82  
P 83  
P 84  
P 85



SLEEPER SLAB

INSPECTOR:

DATE:


PAGE: 3/16

FIELD INSPECTION TEMPLATE

Bridge ID: S12-7 of 25042

\*\*north is into the page.

N/E ABUTMENT



INSPECTOR:


DATE:

PAGE: 12/16

# FIELD INSPECTION TEMPLATE

FOR S12-8 OF 25042 ON I-69 RAMP WB OVER I-75 , GENESEE COUNTY, BAY REGION

- \*\*EXPANSION JOINTS  
ARE DIRT-FILLED AND  
CRACKS SHOWING THAT  
THEY WORK
- \*\*NO STAY-IN-PLACE FOAMS
- \*\*ONLY ONE LANE  
OF TRAFFIC



INSPECTOR:

DATE: 11/05/06


PAGE: 1/ 16

FIELD INSPECTION TEMPLATE

Bridge ID: S12-8 of 25042

\*\*north is out of the page.

S/ W ABUTMENT



INSPECTOR:


DATE:

PAGE: 13/16

SW APP SLAB


# FIELD INSPECTION TEMPLATE

Bridge ID: S12-8 of 25042



S/W APPROACH SLAB

DIRT-FILLED



INSPECTOR:

DATE: 11/05/06


PAGE: 2/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-8 of 25042

BRIDGE DECK

S/W SPAN 1

S/W SPAN 1



INSPECTOR:

DATE:


PAGE: 4/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-8 of 25042

S/W SPAN 2

BRIDGE DECK

S/W SPAN 2



INSPECTOR:

DATE:

PAGE: 5/16




FIELD INSPECTION TEMPLATE  
Bridge ID: S12-8 of 25042

BRIDGE DECK

S/W SPAN 3

S/W SPAN 3



INSPECTOR:

DATE:


PAGE: 6/16

FIELD INSPECTION TEMPLATE  
Bridge ID: S12-8 of 25042

BRIDGE DECK

S/W SPAN 4

S/W SPAN 4




INSPECTOR:

DATE:


PAGE: 7/16

N/E APP SLAB

FIELD INSPECTION TEMPLATE  
 Bridge ID: S12-8 of 25042



N/E APPROACH SLAB



INSPECTOR:

DATE: 11/05/06

PAGE: 3/16

P 44 P 48  
 P 45 P 49  
 P 46 P 50  
 P 47

N/E ABUTMENT

Diagram illustrating the facade structure and joint crack locations. The facade is divided into three vertical sections labeled EBM3, EBM2, and EBM1. The diagram shows the location of joint cracks and points of interest (P 51, P 52, P 53, P 54, P 55, P 56, P 58, P 59, P 61, P 60, P 62, P 63, P 64, P 65, P 66, P 67) relative to the joint cracks. The text "JOINT CRACK" is present in the middle section.

INSPECTOR:

DATE:

PAGE: 12/16

## APPENDIX C

### (a) I-75 over 13 Mile Road



North Bound



South Bound

**Photo C - 1. I-75 over 13 mile road**



(a) Saw cut on the link slab above the pier centerline



(b) Full depth link slab cracks – deck overhang  
North Bound



South Bound

**Photo C - 2. Link slab condition**



North Bound



South Bound

(a) Debris filled expansion joint



North Bound



South Bound

(b) Cracks on debris filled expansion joint

**Photo C - 3. Expansion joint condition**



North Bound



South Bound

**Photo C - 4. Diagonal cracking at the bridge deck corner**



**Photo C - 5. Sleeper slab condition (I-75 south bound)**





**Photo C - 6. Abutment condition of I-75 north bound**





**Photo C - 7. Abutment condition of I-75 south bound**

**(b) S08 of 41027 (I-196 EB over Monroe Ave)**



**Photo C - 8. I-196 EB over Monroe avenue**



**(a) (b)**

**Photo C - 9. (a) Bridge deck underside and (b) link slab underside**



**Photo C - 10. Abutment wall cracking**




**Photo C - 11. Deformed bearing**

**(c) B01 of 10042 (M-115 over Betzie river)**



**Photo C - 12. M-115 over Betzie river**



**Photo C - 13. Link slab cracking**





**Photo C - 14. Approach slab cracking**



**Photo C - 15. Expansion joints**



(a) Abutment wall

(b) Backwall

**Photo C - 16. Cracking of (a) abutment wall and (b) backwall**

**(d) S12-3, 4 of 25042 (I-69 EB and WB over I-75)**



**Photo C - 17. I - 69 EB and WB bridges and EB and WB ramp bridges**



**(a) I - 69 EB**

**(b) I - 69 WB**

**Photo C - 18. Link slab condition of I - 69 (a) EB and (b) WB**



**Photo C - 19. Saw cut provided on the link slab over the pier (I-69 EB)**



**Photo C - 20. Approach slab cracking over the abutment (I-69 EB)**



**Photo C - 21. Debris filled joint with cracks (I-69 EB)**





**Photo C - 22. Transverse and diagonal cracks on I-69 EB bridge deck**



**(a) I-69 EB**

**(b) I-69 WB**

**Photo C - 23. Abutment and pier cap conditions**


**(e) S12-7, 8 of 25042 (I-69 EB and WB ramps over I-75)**



**(a) I – 69 EB Ramp**

**(b) I – 69 WB Ramp**

**Photo C - 24. Link slab condition (a) I-69 EB ramp and (b) I-69 WB ramp**



**(a) I – 69 EB Ramp**

**(b) I – 69 WB Ramp**

**Photo C - 25. Saw cut on link slab over the piers**



(a) I – 69 EB Ramp

(b) I – 69 WB Ramp

**Photo C - 26. Approach slab condition of I-69 (a) EB ramp and (b) WB ramp**



(a) I – 69 EB Ramp

(b) I – 69 WB Ramp

**Photo C - 27. Expansion joint condition of I-69 (a) EB ramp and (b) WB ramp**





(a) I – 69 EB Ramp

(b) I – 69 WB Ramp

**Photo C - 28. Abutment wall condition of I-69 (a) EB ramp and (b) WB ramp**



(a) I – 69 EB Ramp







(b) I – 69 WB Ramp

**Photo C - 29. Backwall cracking at the vicinity of bearings**

## APPENDIX D

**Table D-1. Inspector Comments on Abutment Condition of S04-1-63174**

Inspection Date	Inspector Comments - Abutment Conditions	
	North Abutment	South Abutment
6/25/1999	Vertical cracks & incipient spall under beam 4W.	Vertical cracks & incipient spall under beam 2W.
6/30/2000	Vertical cracks & incipient spall under beam 4W.	Vertical cracks & incipient spall under beam 2W.
9/26/2001	Under Construction.	Under Construction.
2/25/2002	Vertical cracks. Incipient spall at beam 7W.	Patched areas on NE area. Vertical cracks.
2/24/2004	Vertical cracks. Incipient spall at beam 7W.	Patched areas on NE area. Vertical cracks.
2/17/2006	Vertical cracks. Incipient spall at beam 7W.	Patched areas on NE area. Vertical cracks.
12/3/2006	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 1W, 3W, 4W, 8W. Beam 1W bottom flange delamination close to bearing. Abutment wall cracks, delamination and incipient spall at beam 7W.	Abutment wall vertical cracks under beams 2W, 3W, 4W, 6W, 7W, 8W. Abutment wall repair under bm 2W. Horizontal backwall crack near bearing bm 1W. Abutment wall D-cracks and incipient spall under beam 2W









North Abutment	South Abutment
 <p data-bbox="414 730 636 758">Crack in beam 1W</p>	 <p data-bbox="894 527 1347 554">Horizontal backwall crack at beam 1W</p>
 <p data-bbox="358 1297 691 1325">Vertical crack under bm 1W</p>	 <p data-bbox="878 968 1364 1031">Abutment wall D-crack with incipient spall under beam 2W</p>
 <p data-bbox="248 1717 802 1772">Delamination, cracks, incipient spall, and patch work under beam 7W</p>	 <p data-bbox="943 1417 1299 1444">Vertical crack under beam 7W</p>

**Photo D-1. Abutment Distress of S04-01-63174**

**Table D-2. Inspector Comments on Abutment Condition of S04-2-63174**

<b>Inspection Date</b>	<b>Inspector Comments - Abutment Conditions</b>	
	<b>North Abutment</b>	<b>South Abutment</b>
6/25/1999	Vertical cracks & incipient spall under beam 5W.	Repaired area under beam 5W.
6/30/2000	Vertical cracks & incipient spall under beam 5W.	Repaired area under beam 5W.
6/9/2001	No inspector comments.	No inspector comments.
3/13/2002	Patched and waterproofed. Crack under beam 1W.	Patched and waterproofed.
2/24/2004	Patched and waterproofed. Crack under beam 1W.	Patched and waterproofed.
2/17/2006	No inspector comments.	No inspector comments.
12/3/2006	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 3W, 4W, and 7W. Horizontal backwall cracks near bearing of beam 3W. Abutment wall patched under beam 5W. Abutment wall D-cracks and incipient spall under beams 1W, 5W, and 6W.	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 1W, 5W, 6W, 7W, and 8W. Abutment wall patched under beam 4W. Cracks and delamination on abutment wall under beam 4W. Cracks, delamination, and incipient spall under beam 5W. Horizontal backwall cracks near beam 9W bearing. Abutment wall D-cracks and incipient spall under beam 9W.







North Abutment	South Abutment
 <p data-bbox="215 552 841 583">Abutment wall D-crack and incipient spall - beam 1W</p>	 <p data-bbox="963 552 1325 583">Vertical crack under beam 1W</p>
 <p data-bbox="280 951 773 982">Horizontal and vertical cracks at beam 3W</p>	 <p data-bbox="930 951 1357 1003">Cracks and patch work at beam 4W. Horizontal backwall crack</p>
 <p data-bbox="240 1350 821 1381">Abutment wall delamination and spall - beam 5W</p>	 <p data-bbox="906 1350 1382 1402">Delamination, incipient spall, and vertical crack under beam 5W.</p>
 <p data-bbox="215 1728 841 1759">Abutment wall D-crack and incipient spall - beam 6W</p>	 <p data-bbox="930 1728 1357 1801">Abutment wall D-crack and backwall horizontal cracks at beam 9W</p>

**Photo D-2. Abutment Distress of S04-02-63174**

**Table D-3. Inspector Comments on Abutment Condition of S08 - 41027**







Inspection Date	Inspector Comments - Abutment Conditions	
	Northwest Abutment	Southeast Abutment
9/24/1999	Backwall has horizontal leach crack. Below bearings, couple vertical cracks.	Couple wet areas in backwall. Below bearings, couple vertical cracks.
11/1/1999	Backwall has large vertical leach crack. Below bearings, couple vertical cracks.	Couple wet areas in backwall. Below bearings, couple vertical cracks.
11/30/2001	Backwall has large vertical leach crack. Below bearings, couple vertical cracks.	Couple wet areas in backwall. Below bearings, couple vertical cracks.
5/15/2003	Typical vertical cracks. Wet leaching cracks in top of backwalls.	Typical vertical cracks. Wet leaching cracks in top of backwalls.
4/13/2005	Typical vertical cracks. Wet leaching cracks in top of backwalls.	Typical vertical cracks. Wet leaching cracks in top of backwalls.
12/19/2005	Some abut repairs made 2005. Good Condition.	Some abut repairs made 2005. Good Condition.
11/4/2006	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 3W and 8W. Deformed bearing under beam 6W.	Abutment wall vertical cracks. Abutment wall cracking on SW face under backwall. Abutment wall vertical cracks under beam 4W.

Northwest Abutment	Southeast Abutment
 <p>Side crack on SW side underneath the backwall</p>  <p>Vertical crack under beam 4W</p>	 <p>Vertical crack under beam 3W</p>  <p>Deformation of bearing beam 6W</p>

**Photo D-3. Abutment Distress of S08-51027**

**Table D-4. Inspector Comments on Abutment Condition of B01 - 10042**




<b>Inspection Date</b>	<b>Inspector Comments--Abutment Conditions</b>	
	<b>Northwest Abutment</b>	<b>Southeast Abutment</b>
10/6/1996	No inspector comments.	No inspector comments.
10/18/2000	Vertical cracks.	Vertical cracks.
7/30/2002	Vertical cracks.	Vertical cracks.
10/12/2004	Vertical cracks.	Vertical cracks.
11/4/2006	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 1W, 2W, 3W, 4W, 6W, and 7W. Backwall cracking in the vicinity of beams 3W, 5W, and 6W.	Abutment wall vertical cracks. Abutment wall vertical cracks under beams 1W, 2W, 3W, 4W, 7W, and 8W. Diagonal backwall crack between beams 1W and 2W.

Northwest Abutment	Southeast Abutment
 <p data-bbox="321 583 680 615">Vertical crack under beam 2W</p>  <p data-bbox="224 940 777 1003">Vertical crack under 3W and backwall cracking near beam end</p>  <p data-bbox="305 1360 696 1392">Backwall crack next to beam 5W</p>  <p data-bbox="280 1728 721 1759">Horizontal crack at bearing beam 6W</p>	 <p data-bbox="943 583 1302 615">Vertical crack under beam 1W</p>  <p data-bbox="837 972 1408 1035">Diagonal backwall crack between beam 1W and 2W</p>

**Photo D-4. Abutment Distress of B01 - 10042**

**Table D-5. Inspector Comments on Abutment Condition of S12-3-25042**

Inspection Date	Inspector Comments--Abutment Conditions	
	Northeast Abutment	Southwest Abutment
10/24/1996	A few vertical cracks in abut wall.	A few vertical cracks in abut wall.
10/20/2000	A few vertical cracks in abut wall. Concrete appears sound.	A few vertical cracks in abut wall. Concrete appears sound.
10/3/2002	A few vertical cracks in abut wall. Concrete appears sound.	A few vertical cracks in abut wall. Concrete appears sound.
10/27/2004	A few vertical cracks in abut wall.	A few vertical cracks in abut wall.
11/5/2006	Vertical cracking on abutment wall. Vertical abutment wall cracking near bm 1W. Backwall concrete spall at bearing of beam 4W.	Vertical cracking on abutment wall. Vertical abutment wall cracking near beams 2W and 4W.









Northeast Abutment	Southwest Abutment
 <p>Vertical crack under beam 1W</p>  <p>Spall at bearing under beam 4W</p>	 <p>Vertical crack under beam 2W</p>

**Photo D-5. Abutment Distress of S12-3-25042**

**Table D-6. Inspector Comments on Abutment Condition of S12-4-25042**

<b>Inspection Date</b>	<b>Inspector Comments--Abutment Conditions</b>	
	<b>Northeast Abutment</b>	<b>Southwest Abutment</b>
10/24/1996	Vertical cracks in abut wall.	Vertical cracks in abut wall.
10/20/2000	Vertical cracks in abut wall. Concrete appears sound.	Vertical cracks in abut wall. Concrete appears sound.
10/7/2002	Vertical cracks in abut wall. Concrete appears sound.	Vertical cracks in abut wall. Concrete appears sound.
4/3/2004	Vertical cracks in abut wall. Concrete appears sound.	Vertical cracks in abut wall. Concrete appears sound.
11/5/2006	Vertical abutment wall cracking between beams. Vertical abutment wall cracking near beams 1W and 4W. Backwall cracking at bearing of beams 1W, 3W, and 4W.	Vertical abutment wall cracks between beams. Vertical abutment wall cracking near beams 1W and 2W. Beam end spalling near bearing of beam 1W. Horizontal backwall cracking near bearing of beams 2W, 3W, and 4W.








Northeast Abutment	Southwest Abutment
 <p data-bbox="240 583 764 646">Vertical abutment wall cracking and backwall cracking near bearing of beam 1W</p>	 <p data-bbox="943 583 1302 615">Vertical crack under beam 1W</p>
 <p data-bbox="269 1014 732 1045">Horizontal backwall cracks at beam 3W</p>	 <p data-bbox="951 972 1294 1003">Spalling at beam bearing 1W</p>
 <p data-bbox="321 1339 673 1371">Vertical crack under beam 4W</p>	 <p data-bbox="849 1350 1396 1381">Horizontal backwall crack at beam bearing 2W</p>
 <p data-bbox="212 1675 789 1707">Loss of bearing and backwall cracks at beam 4W</p>	 <p data-bbox="906 1707 1339 1738">Beam end spall at beam bearing 4W</p>

**Photo D-6. Abutment Distress of S12-4-25042**

**Table D-7. Inspector Comments on Abutment Condition of S12-7-25042**

<b>Inspection Date</b>	<b>Inspector Comments--Abutment Conditions</b>	
	<b>Northeast Abutment</b>	<b>Southwest Abutment</b>
10/24/1996	A few cracks in abutment wall.	A few cracks in abutment wall.
10/20/2000	A few cracks in abutment wall. Concrete appears sound.	A few cracks in abutment wall. Concrete appears sound.
10/3/2002	A few cracks in abutment wall. Concrete appears sound. Will function as designed.	A few cracks in abutment wall. Concrete appears sound. Will function as designed.
10/28/2004	A few cracks in abutment wall.	A few cracks in abutment wall.
11/5/2006	Vertical abutment wall cracks between beams. Vertical abutment wall cracks near beams 1W and 2W. Beam end and backwall cracking in the vicinity of bearing of beam 3W.	Vertical abutment wall cracks between beams. Beam end spall in the vicinity of the bearing of beam 1W. Horizontal backwall cracking near bearing of beams 1W and 2W.







Northeast Abutment	Southwest Abutment
 <p>Horizontal backwall and vertical abutment wall cracks at beam 1W</p>  <p>Vertical abutment wall crack under beam 2W</p>  <p>Crack at bearing under beam 3W</p>	 <p>Beam end spall and backwall cracks at bearing of beam 1W</p>  <p>Horizontal backwall crack at beam bearing 2W</p>

**Photo D-7. Abutment Distress of S12-7-25042**

**Table D-8. Inspector Comments on Abutment Condition of S12-8-25042**

Inspection Date	Inspector Comments - Abutment Conditions	
	Northeast Abutment	Southwest Abutment
10/24/1996	Vertical cracks in abutment wall.	Vertical cracks in abutment wall.
10/20/2000	Several vertical cracks in abutment wall. Concrete appears sound.	Several vertical cracks in abutment wall. Concrete appears sound.
10/7/2002	Several vertical cracks in abutment wall. Concrete appears sound.	Several vertical cracks in abutment wall. Concrete appears sound.
10/28/2004	Tight vertical cracks in abutment wall.	Tight vertical cracks in abutment wall.
11/5/2006	Vertical abutment wall cracking between beams. Vertical abutment wall cracking near beam 2W. Beam end spalling near bearing of beam 2W. Beam and cracking near bearing of beam 3W.	Vertical abutment wall cracking between beams. Beam end cracking near bearing of beams 1W, 2W, and 3W. Backwall cracking near bearing of beam 3W.

Northeast Abutment	Southwest Abutment
 <p>Vertical cracks under beam 2W</p>	 <p>Beam end crack near beam bearing 1W</p>
 <p>Beam end crack near beam bearing 3W</p>	 <p>Crack in beam 3W and horizontal backwall crack</p>

**Photo D-8. Abutment Distress of S12-8-25042**

## APPENDIX E

**Table E-1. Moments and Axial Forces for Different Debonded Lengths**

Debonded %		0.00%	2.50%	5.00%	7.50%
<b>L<sub>1</sub> (HRRR)</b>	<b>M (ft-k)</b>	-193	-83	-51	-34
	<b>N (k)</b>	0	0	0	0
<b>L<sub>2</sub> (RHHR)</b>	<b>M (ft-k)</b>	-63	-28	-19	-13
	<b>N (k)</b>	151	157	159	160
<b>L<sub>3</sub> (RRHR)</b>	<b>M (ft-k)</b>	-193	-83	-51	-34
	<b>N (k)</b>	0	0	0	0
<b>TP<sub>1</sub> (HRRR)</b>	<b>M (ft-k)</b>	142	80 61	53	
	<b>N (k)</b>	0	0 0 0		
<b>TP<sub>2</sub> (RHHR)</b>	<b>M (ft-k)</b>	74	50 44	42	
	<b>N (k)</b>	-79	-86 -84	-87	
<b>TP<sub>3</sub> (RRHR)</b>	<b>M (ft-k)</b>	142	80 61	53	
	<b>N (k)</b>	0	0 0 0		
<b>TN<sub>1</sub> (HRRR)</b>	<b>M (ft-k)</b>	-43	-24	-18	-16
	<b>N (k)</b>	0	0	0	0
<b>TN<sub>2</sub> (RHHR)</b>	<b>M (ft-k)</b>	-22	-15	-13	-13
	<b>N (k)</b>	24	26	25	26
<b>TN<sub>3</sub> (RRHR)</b>	<b>M (ft-k)</b>	-43	-24	-18	-16
	<b>N (k)</b>	0	0	0	0




Figure E-1. Stresses YY distribution along the width for  $L_1$  case for one lane straight full bridge




Figure E-2. Stresses YY distribution along the width for  $L_2$  case for one lane straight full bridge




Figure E-3. Stresses YY distribution along the width for  $L_3$  case for one lane straight full bridge




Figure E-4. Stresses YY distribution along the width for T<sub>1</sub> case for one lane straight full bridge




Figure E-5. Stresses YY distribution along the width for T<sub>2</sub> case for one lane straight full bridge






Figure E-6. Stresses YY distribution along the width for  $T_3$  case for one lane straight full bridge




Figure E-7. Stresses YY distribution along the width for  $L_1$  case for two lane straight full bridge




Figure E-8. Stresses YY distribution along the width for  $L_2$  case for two lane straight full bridge




Figure E-9. Stresses YY distribution along the width for  $L_3$  case for two lane straight full bridge




Figure E-10. Stresses YY distribution along the width for  $T_1$  case for two lane straight full bridge




Figure E-11. Stresses YY distribution along the width for T<sub>2</sub> case for two lane straight full bridge




Figure E-12. Stresses YY distribution along the width for T<sub>3</sub> case for two lane straight full bridge




Figure E-13. Stresses YY distribution along the width for  $L_1$  case for one lane 20° skew full bridge (parallel to skew angle)






Figure E-14. Stresses YY distribution along the width for  $L_2$  case for one lane 20° skew full bridge (parallel to skew angle)




Figure E-15. Stresses YY distribution along the width for L<sub>3</sub> case for one lane 20° skew full bridge (parallel to skew angle)




Figure E-16. Stresses YY distribution along the width for  $T_1$  case for one lane 20° skew full bridge (parallel to skew angle)




Figure E-17. Stresses YY distribution along the width for  $T_2$  case for one lane 20° skew full bridge (parallel to skew angle)




Figure E-18. Stresses YY distribution along the width for  $T_3$  case for one lane  $20^\circ$  skew full bridge (parallel to skew angle)




Figure E-19. Stresses YY distribution along the width for  $L_1$  case for two lane 20° skew full bridge (parallel to skew angle)




Figure E-20. Stresses YY distribution along the width for  $L_2$  case for two lane 20° skew full bridge (parallel to skew angle)




Figure E-21. Stresses YY distribution along the width for  $L_3$  case for two lane 20° skew full bridge (parallel to skew angle)






Figure E-22. Stresses YY distribution along the width for T<sub>1</sub> case for two lane 20° skew full bridge (parallel to skew angle)




Figure E-23. Stresses YY distribution along the width for T<sub>2</sub> case for two lane 20° skew full bridge (parallel to skew angle)

## **APPENDIX F**

### **DESIGN PROCEDURE FOR LINK SLABS**

#### ***DESIGN MOMENT***

Design Procedure described in the appendix will follow the rationale developed by Caner and Zia (1998). AASHTO LRFD (2004) requires forces calculated from the combined effects of live and thermal loads for the service limit state design. Link slab design moments are calculated using the girder end rotations. HL-93 loading is used to calculate the girder end rotations under live load. Girder end rotations caused by temperature gradient are calculated using the procedure described by Saadeghvaziri and Hadidi (2002).

First step of the load analysis is to establish composite girder-deck cross-section with an effective width as per AASHTO LRFD (2004) Section 4.6.2.6, the composite moment of inertia, and define the modulus of elasticity for concrete.

#### **Girder End Rotations due to Live Load**


AASHTO LRFD (2004) procedures are followed:

Apply HL-93 loading [HS-20 truck with impact and distribution factor (LRFD section 3.6.2.1 and 4.6.2.2.2) + 0.64 kips/ft lane loading (LRFD 3.6.1.2.4)] on the simply supported spans to compute maximum girder end rotations (Note: the position of the truck is not necessarily coincident with positions that lead to either maximum midspan moment or deflection).


#### **Girder End Rotations due to Temperature Gradient**

The girder-deck composite cross-section is subjected to temperature gradient as described in AASHTO LRFD section 3.12.3 (Figure F-1).

Figure F-2 illustrates the strain compatibility of the sections, associated forces and moments developed in the sections and the temperature gradient profile along the depth of the cross-section.



**Figure F-1. Temperature profile along cross-section**



**Figure F- 2. Compatibility forces and moments and temperature profile along cross-section height**

### Strain Compatibility

Using the relationship between forces and strains and using strain compatibility between sections 1 and 2, the following relationship is obtained;

$$\begin{aligned}\epsilon_{Bottom1} &= \alpha_1(T_2) + \frac{M_1}{E_1 S_{b1}} + \frac{F_1}{E_1 A_1} + \frac{F_1 d_{b1}}{E_1 S_{b1}} = \epsilon_{Top2} \\ \epsilon_{Top2} &= \alpha_2(T_2) + \frac{M_2 - M_1}{E_2 S_{t2}} + \frac{F_2 - F_1}{E_2 A_2} + \frac{F_2 d_{b2} + F_1 d_{t2}}{E_2 S_{t2}}\end{aligned}\quad (F-1)$$

Repeating the formulation with using the strain compatibility between sections 2 and 3;

$$\begin{aligned}\varepsilon_{Bottom2} &= \alpha_2(T_3) + \frac{M_2 - M_1}{E_2 S_{b2}} + \frac{F_2 - F_1}{E_2 A_2} + \frac{F_2 d_{b2} + F_1 d_{t2}}{E_2 S_{b2}} = \varepsilon_{Top3} \\ \varepsilon_{Top3} &= \alpha_3(T_3) + \frac{M_3 - M_2}{E_3 S_{t3}} + \frac{F_3 - F_2}{E_3 A_3} + \frac{F_3 d_{b3} + F_2 d_{t3}}{E_3 S_{t3}}\end{aligned}\quad (F-2)$$

Repeating the formulation with using the strain compatibility between sections 3 and 4;

$$\begin{aligned}\varepsilon_{Bottom3} &= \alpha_3(T_4) + \frac{M_3 - M_2}{E_3 S_{b3}} + \frac{F_3 - F_2}{E_3 A_3} + \frac{F_3 d_{b3} + F_2 d_{t3}}{E_3 S_{b3}} = \varepsilon_{Top4} \\ \varepsilon_{Top4} &= \alpha_4(T_4) - \frac{M_3}{E_4 S_{t4}} - \frac{F_3}{E_4 A_4} + \frac{F_3 d_{t4}}{E_4 S_{t4}}\end{aligned}\quad (F-3)$$

### Curvature Compatibility

Curvature compatibility between sections provides the following relationships:

Between sections 1 and 2;

$$\begin{aligned}\frac{1}{R_1} &= \alpha_1\left(\frac{T_2 - T_1}{h_1}\right) + \frac{M_1}{E_1 I_1} + \frac{F_1 d_{b1}}{E_1 I_1} = \frac{1}{R_2} \\ \frac{1}{R_2} &= \alpha_2\left(\frac{T_3 - T_2}{h_2}\right) + \frac{M_2 - M_1}{E_2 I_2} + \frac{F_1 d_{t2} + F_2 d_{b2}}{E_2 I_2}\end{aligned}\quad (F-4)$$

Between sections 2 and 3;

$$\begin{aligned}\frac{1}{R_2} &= \alpha_2\left(\frac{T_3 - T_2}{h_2}\right) + \frac{M_2 - M_1}{E_2 I_2} + \frac{F_1 d_{t2} + F_2 d_{b2}}{E_2 I_2} = \frac{1}{R_3} \\ \frac{1}{R_3} &= \alpha_3\left(\frac{T_4 - T_3}{h_3}\right) + \frac{M_3 - M_2}{E_3 I_3} + \frac{F_2 d_{t3} + F_3 d_{b3}}{E_3 I_3}\end{aligned}\quad (F-5)$$

Between sections 3 and 4;

$$\begin{aligned}\frac{1}{R_3} &= \alpha_3\left(\frac{T_4 - T_3}{h_3}\right) + \frac{M_3 - M_2}{E_3 I_3} + \frac{F_2 d_{t3} + F_3 d_{b3}}{E_3 I_3} = \frac{1}{R_4} \\ \frac{1}{R_4} &= \alpha_4\left(\frac{T_5 - T_4}{h_4}\right) - \frac{M_3}{E_4 I_4} + \frac{F_3 d_{t4}}{E_4 I_4}\end{aligned}\quad (F-6)$$

where

$\alpha_i$  : Coefficient of thermal expansion for Section i

$T_i$  : Girder and deck temperature changes as given in Figure F-1 and Figure F- 2

$F_i$  : Force resultant of stresses between section i and i+1

$M_i$  : Moment resultant of stresses between section i and i+1

$d_{bi}$  : Distance from centroid to bottom fiber of Section i

$d_{ti}$  : Distance from centroid to top fiber of Section i

$S_{bi}$  : Bottom section modulus for Section i

$S_{ti}$  : Top section modulus for Section i

$E_i$  : Modulus of elasticity of Section i

$A_i$  : Cross-sectional area of Section i

$I_i$  : Moment of inertia of Section i

Solving the above six equations F-1 through F-6 simultaneously for six unknowns ( $F_1$ ,  $F_2$ ,  $F_3$ ,  $M_1$ ,  $M_2$ ,  $M_3$ ), and plugging the forces back into F-4, F-5 and F-6 curvature values can be obtained.

End-slopes can be obtained from curvatures by integrating along the length as given below;

$$\frac{d\theta}{dx} = \frac{1}{R_1} = \frac{1}{R_2} = \frac{1}{R_3} = \frac{1}{R_4} = \frac{1}{R} \quad \theta(x) = \int \frac{1}{R} dx = \frac{x}{R} + C_1 \quad (\text{F-7})$$

Eq. F-7 includes an integration constant  $C_1$ . For a simply supported span with length  $L$ , and since the slope at mid-span is zero due to symmetry under gradient loading, integration constant  $C_1$  can be evaluated as;

$$\theta\left(\frac{L}{2}\right) = \frac{L}{2R} + C_1 = 0 \quad C_1 = -\frac{L}{2R} \quad (\text{F-8})$$

Then, the slope equation and the slope at the beam end will be equal to;

$$\theta(x) = \frac{x}{R} - \frac{L}{2R} \quad \theta(L) = \frac{L}{R} - \frac{L}{2R} = \frac{L}{2R} \quad (\text{F-9})$$

Link slab moment can be calculated from the girder end rotations under live and thermal gradient loads as given below:

$$M_a = \frac{2E_c I_d \theta}{L_L} \quad (\text{F-10})$$

where,

$I_d$  : Moment of inertia of the link slab

$L_L$  : Length of the link slab (Debond zone length: sum of 5 % of each adjacent girder span + gap distance between beam ends)

### ***DESIGN AXIAL FORCE***

For a two-span system with RHHR supports, tensile force developed in the link slab would be equal to the horizontal reactions at the interior supports. The horizontal reaction is equal to the continuity moment divided by the distance between the centroid of deck and bearing location (Figure F-3).




Figure F-3. Effect of RHHR type support condition on continuity (Okeil and El-Safty 2005)

### **Continuity Moment due to Live Load**

Under live load, each span is loaded so as to create maximum negative moment at the interior support (Figure F-4) with composite cross-section properties. Any structural analysis program can be used to perform this analysis.




Figure F-4. Continuity moment at the interior support under live load

### **Continuity Moment due to Temperature Gradient**

For a two-span-continuous system with constant cross-section in both spans, continuity moment  $M_{continuity}$  can be calculated as;

$$M_{continuity} = \frac{(F_2 d_{tg} - M_3)(3E_{Composite} I_{Composite})}{2E_{Girder} I_{Girder}} \quad (F-11)$$

where

$F_2$  : Force resultant of stresses between section 2 and 3 calculated from six simultaneous equations

$M_3$  : Moment resultant of stresses between section 2 and 3 calculated from six simultaneous equations

$d_{tg}$  : Distance from centroid to top fiber of girder

$E_{Composite}$  : Modulus of elasticity of composite section

$I_{Composite}$  : Moment of inertia of composite section

$E_{Girder}$  : Modulus of elasticity of girder

$I_{Girder}$  : Moment of inertia of girder

Once the continuity moment is found, tensile force in the link slab is;

$$T = \frac{M_{continuity}}{h} \quad (F-12)$$

where  $h$  is the distance between the centroid of deck and the top of the bearing.



## Numerical Example

Cross-section properties of the girder and the composite section are given in Figure F- 5.




Figure F- 5. Girder and composite section geometric properties

The compressive strength of the girder and deck concrete ( $f'_c$ ) = 5000 psi.

Concrete modulus of elasticity ( $E_c$ ) = 4031 ksi.

Reinforcement yield strength ( $f_y$ ) = 60 ksi.

The deck overhang = 30 in. (on either side of the beam).

Composite inertia ( $I_{\text{composite}}$ ) = 392,892 in<sup>4</sup>.

## DESIGN MOMENT

### Live Load:

HL-93 (AASHTO LRFD 2004) loading is applied at a location to create maximum end rotation on the 69.5 ft span of the bridge. The impact factor is taken as 1.33 from Section 3.6.2.1 of AASHTO LRFD (2004). As per Section 3.6.1.3 AASHTO LRFD (2004), lane load of 0.64 k/ft is used in addition to the axle loads. Distribution factor is calculated as 0.571 assuming two or more lanes are loaded from the formulation in AASHTO LRFD (2004) Table 4.6.2.2.2b-1.

From the analysis maximum end rotation is calculated as 0.00154 radians when front axle is located 18.4 feet away from the end of the span.

Link slab length =  $69.5 \times 12 \times 5\% \times 2 + 1$  in. gap = 84.4 inches

Gross moment of inertia of concrete link slab = 4617 in<sup>4</sup>

Moment induced by live load:

$$M_a = \frac{2E_c I_d \theta}{L_L} = \frac{2 \times 4031 \times 4617 \times 0.00154}{84.4 \times 12} = -56.6 \text{ ft.kips}$$

for 76 in. wide effective section or

$$M_a = \frac{2E_c I_d \theta}{L_L} = \frac{2 \times 4031 \times 729 \times 0.00154}{84.4 \times 12 \times (76/12)} = -8.9 \text{ ft} - \frac{\text{kips}}{\text{ft}}$$

Moment induced by temperature Gradient Loading:

$$b_1 = 76 \text{ in.}, b_2 = 16 \text{ in.}$$

$$h_1 = 4 \text{ in.}, h_2 = 5 \text{ in.}, h_3 = 7 \text{ in.}, h_4 = 38 \text{ in.}$$

$$T_1 = 41^\circ\text{F}, T_2 = 11^\circ\text{F}, T_3 = 6.42^\circ\text{F}, \quad \text{Positive temperature gradient (LRFD 3.12.3)} \\ T_4 = T_5 = 0$$

$$E_c = 5000 \text{ ksi and } \alpha = 6 \text{ E-6 in./in./}^\circ\text{F for both deck and girder concrete}$$

For section 4 of Figure F-1:

$$A_4 = 447.5 \text{ in}^2, I_4 = 61889.67 \text{ in}^4, d_{t4} = 23.09 \text{ in.}, S_{t4} = 2680 \text{ in}^3$$

$$L_L = 84.4 \text{ in. and } I_d = 4617 \text{ in}^4 \text{ for the } 76 \text{ in.} \times 9 \text{ in. deck cross-section}$$

Solving simultaneous equations F-1 through F-6, internal forces and moments can be calculated as:

$$F_1 = -48.15 \text{ kips}, F_2 = 32.90 \text{ kips}, F_3 = 51.53 \text{ kips} \\ M_1 = 195.31 \text{ in-kips}, M_2 = 270.47 \text{ in-kips}, M_3 = -3.61 \text{ in.kips}$$

Then, the curvature can be calculated from any equation F-4 through F-6.

$$\frac{d\theta}{dx} = \frac{1}{R_1} = \frac{1}{R_2} = \frac{1}{R_3} = \frac{1}{R_4} = \frac{1}{R} = 3.857 \times 10^{-6}$$

Then, the end rotation can be calculated with equation F-9.

$$\theta(L) = \frac{L}{R} - \frac{L}{2R} = \frac{L}{2R} = \frac{834}{2} \times 3.857 \times 10^{-6} = 1.638 \times 10^{-3} \text{ rad}$$

Finally, moment generated by positive temperature gradient load, according to equation F-10 is:

$$M_a = \frac{2E_c I_d \theta}{L_L} = \frac{2 \times 4031 \times 4617 \times 1.608 \times 10^{-3}}{84.4 \times 12} = 59.1 \text{ ft.kips}$$

for 76 in. wide effective section or

$$M_a = \frac{2E_{cd} \theta}{L_L} = \frac{2 \times 4031 \times 729 \times 1.608 \times 10^{-3}}{84.4 \times 12 \times (76/12)} = 9.4 \text{ ft - kips/ft}$$

Moment caused by negative thermal gradient will be -0.3 times the positive gradient loading.

$$M_a = 59.1 \times -0.3 = -17.7 \text{ ft.kips for 76 in. wide effective section or}$$

$$M_a = 9.4 \times -0.3 = -2.8 \text{ ft.kips / ft}$$

#### Load Combinations:

Thermal gradient loading [i.e., negative thermal gradient (NTG) and positive thermal gradient (PTG)] and live load need to be combined to create critical load combinations.

Service I-NTG: 1.0 Live Load + 0.5 Negative Thermal Gradient

Service I-PTG: 1.0 Positive Thermal Gradient

Service I-NTG Load Combination:

$$M_a = -56.6 + 0.5 \times -17.7 = -65.5 \text{ ft.kips} = -10.35 \text{ ft.kips / ft}$$

Service I-PTG Load Combination:

$$M_a = 59.1 \text{ ft.kips} = 9.34 \text{ ft.kips / ft}$$

#### Cracking Moment:

Using AASHTO LRFD section 5.4.2.6 and 5.7.3.6.2

$$f_r = 536 \text{ psi } (0.24 \sqrt{f'_c}, \text{ksi}) \text{ and } M_{cr} = f_r I_g / y = 7.2 \text{ ft-kips / ft}$$

$$M_a > M_{cr} \quad \text{Slab will crack. In that case relief cut is required.}$$

#### Negative Moment Reinforcement (i.e., top fiber in tension)

Based on allowable stress limit in the reinforcement per AASHTO LRFD section 5.7.3.4, and assuming d = 6.7 inches, an area of steel of 0.793 in.<sup>2</sup>/ft is required for a moment of -10.35 ft-kips/ft.

$$\text{Use \#6 bars @ 6 inches} = A_{steel} = 0.88 \text{ in}^2 > 0.793 \text{ in}^2$$

$$f_{steel} = 22.7 \text{ ksi} < f_{allowable} = 32.4 \text{ ksi} \quad z = 91 < 130$$

#### Positive Moment Reinforcement (i.e., bottom fiber in tension)

Based on allowable stress limit in the reinforcement per AASHTO LRFD section 5.7.3.4 and assuming  $d=6.7$  inches, an area of steel of  $0.715 \text{ in}^2/\text{ft}$  is required for a moment of  $9.34 \text{ ft-kips/ft}$ .

$$\text{Use \#6 bars @ 6 inches} = A_{steel} = 0.88 \text{ in}^2 > 0.715 \text{ in}^2$$

$$f_{steel} = 20.5 \text{ ksi} < f_{allowable} = 32.4 \text{ ksi} \quad z = 83 < 130$$

#### **DESIGN AXIAL LOAD**

For RHHR boundary condition, axial force in the link slab needs to be calculated using the maximum negative moment at the interior support of a two-span continuous system. HL-93 (AASHTO LRFD 2004) loading is applied at both spans to create maximum negative moment of  $-724 \text{ ft. kips}$  at the interior support.

Axial force acting on the link slab due to HL-93 loading:

$$T = \frac{M_{continuity}}{h} = \frac{-724 \times 12}{(54 - 9/2)} = -176 \text{ kips} = -27.8 \text{ kips/ft} \quad (\text{Tension})$$

Axial force acting on the link slab due to positive temperature gradient:

$$M_{continuity} = \frac{(F_2 d_{tg} - M_3)(3E_{Composite} I_{Composite})}{2E_{Girder} I_{Girder}} = \frac{(32.89 \times 24.73 + 3.61)(3 \times 4031 \times 392892)}{2 \times 4031 \times 125390} = 3840 \text{ in.kips}$$

$$T = \frac{M_{continuity}}{h} = \frac{3840}{(54 - 9/2)} = 78 \text{ kips} = 12.3 \text{ kips/ft} \quad (\text{Compression})$$

Axial force acting on the link slab due to negative temperature gradient:

$$T_{NG} = -0.3T_{PG} = -0.3 \times 78 = 23.4 \text{ kips} = -3.7 \text{ kips/ft} \quad (\text{Tension})$$


#### **DESIGN LOAD COMBINATIONS**

Service I-NTG Load Combination:


$$M_a = -10.35 \text{ ft.kips/ft} \quad (N = 27.8 + 3.7/2 = 29.7 \text{ kips/ft for RHHR})$$

Service I-PTG Load Combination:

$$M_a = 9.34 \text{ ft.kips / ft} \quad (N = -12.32 \text{ kips / ft for RHHR})$$



**Figure F-6. Moment and Interaction Diagram under Service Loads for unit link slab width**



**Figure F-6. Moment and Interaction Diagram under Service Loads for unit link slab width**

## **APPENDIX G**


Proposed Design Details in MDOT Design Guide Format

DRAWN BY:  
CHECKED BY:  
APPROVED BY:

MICHIGAN DEPARTMENT OF TRANSPORTATION  
BUREAU OF HIGHWAY DEVELOPMENT


PROPOSED TYPICAL SECTION THRU  
INDEPENDENT BACKWALL WITH SLIDING SLAB

ISSUED:  
SUPERSEDES:



\*CONTINUE BOTTOM BARS 24" PAST CONSTRUCTION JOINT INTO THE APPROACH SLAB





TYPICAL SECTION AT BRIDGE APPROACH


\* CONTINUE BOTTOM BARS 24" PAST CONSTRUCTION JOINT INTO THE APPROACH SLAB

DRAWN BY:  
CHECKED BY:  
APPROVED BY:

MICHIGAN DEPARTMENT OF TRANSPORTATION  
BUREAU OF HIGHWAY DEVELOPMENT

## PROPOSED INTEGRAL AND SEMI-INTEGRAL ABUTMENT BACKWALL

ISSUED:  
SUPERSEDES:



PLAN NOTES:

\* WHERE CONSTRUCTION JOINTS ARE USED, THERE WILL BE NO PAYMENT FOR THE REQUIRED JOINT WATERPROOFING.

NOTES:

INTEGRAL AND SEMI-INTERGRAL ABUTMENT BRIDGES SHALL BE CONSIDERED FOR STEEL BRIDGES LESS THAN 300' AND CONCRETE BRIDGES LESS THAN 400' IN LENGTH.


APPROACH SLAB THICKNESS WILL MATCH THE ROAD APPROACH THICKNESS (9" MIN.)

\*\* USE FOR INTEGRAL ABUTMENT BRIDGES ONLY.

SEMI-INTERGRAL ABUTMENTS SHOULD BE USED AT STREAM CROSSINGS.

D = BACKWALL THICKNESS. SEE GUIDE 6.20.01 FOR DEFINITION.

\*\*\* EA06 BAR



PREPARED BY  
WESTERN MICHIGAN  
UNIVERSITY

150  
6.20.04XX